ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	11	Kuvempu Nagar
Street ID	**Street Name**	**Significant Landmark**
W0633, W0554, W0595, W0538, W0593, W0528, W0611, W	NA, 1st Crs, 5th Crs, 1st Main Rd, 6th Crs, 4th Crs	Kuvempunagara 1st Stage
Segment No.	**Total Length (m)**	
11/C-W0633/S013654	972.82	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	72.90	77.538890	13.071935	77.539534	13.071748	W0611	W0593
2	152.16	77.539423	13.071399	77.538095	13.071844	W0611	DEAD END
3	569.96	77.539057	13.070208	77.534043	13.071747	W0611	W0491
4	177.80	77.541355	13.069195	77.539777	13.069630	W0027	W0633

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements and Asphalting to Roads Kuvempunagara 1st Stage in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	3000000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements and Asphalting to Roads Kuvempunagara 1st Stage in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-15-000001
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/222/2015-16	15/02/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
16/02/2016	15/02/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)

Field Inspection Details

Number of Trees	Any Other Information	Name
12		Suresh
Date of Inspection	**Remarks**	
17/06/2016	completed	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0633, W0554, W0595, W0538,

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	18/06/2016	17/07/2016	COMPLETED
SE	VASU K M	18/06/2016	17/07/2016	COMPLETED
EE	YARAPPA REDDY	18/06/2016	17/07/2016	COMPLETED
AEE	SHIVAKUMAR	18/06/2016	17/07/2016	COMPLETED
AE	SURESH	18/06/2016	17/07/2016	COMPLETED
AE	SURESH	17/06/2016	17/07/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0633, W0554, W0595, W0538,